	Туре	#	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition
	BRS	1.5	103	fuse\$1 and (terminal\$1 same cooling) and coolant	USPA	2003/12/1 6 10:40		
	BRS	L6	9	fuse\$1 and (terminal\$1 same cooling) and coolant	EPO; JPO; DERW ENT	2003/12/16 10:42		
	BRS	L7	20	fuse\$1 and (terminal\$1 same cooling) and coolant	US-P GPUB	2003/12/1 6 10:44		
	BRS	18	903	fuse\$1 and (terminal\$1 same cooling)	USPA T	2003/12/1 6 10:44		
	BRS	L9	110	fuse\$1 and (terminal\$1 same cooling same liquid)	USPA T	2003/12/1 6 10:51		
	BRS	L10	96	9 not 5	USPA T	2003/12/1 6 10:45		
pris pris pris pris pris pris pris pris	BRS	L111	7 8	fuse\$1 and (terminal\$1 same cooling same liquid)	US-P GPUB ; EPO; JPO; DERW ENT; IBM	2003/12/1 6 10:54		
	BRS	112	2563	fuse\$1 and (terminal\$1 and cooling and liquid)	US-P GPUB; JPO; JPO; DERW ENT; IBM	2003/12/16 10:55		

0

0

ω

편 다 다 양

0

0

 \sim

 \sim

ഹ

4

Ø

7

0

0

0

0

	Type	# 7	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	E L
თ	BRS	L13	21	fuse\$1 same (terminal\$1 and cooling and liquid)	US-P GPUB FPO; JPO; DERW ENT; IBM TDB	2003/12/1 6 10:56			0
10	BRS	L14 75	75	fuse\$1 same (terminal\$1 and cooling and liquid)	USPA	USPA 2003/12/1 T 6 10:56			
11	BRS	L15	58	14 not 10	USPA T	USPA 2003/12/1 T 6 10:56			0